MODEM CARDS

The following modem cards were tested under Windows™® 95.   Test function includes connecting to the Internet and downloading a file. the Internet and downloading a file.

MANUFACTURER	MODEL NUMBER		RESULT	
	AT&T	ISA	28.8K	OK
	Rockwell	ISA	28.8K	OK
CIS	WS-2814IM5 PnP(Rockwell)	ISA	28.8K	OK
Supra Express	288i PnP (Rockwell)	ISA	28.8K	OK
GVC	QuicklinkII(F-1128HV/TI)	ISA	33.6K	OK
CIS	WS-3314JS3 ASVD PnP(Rockwell)	ISA	33.6K	OK
Supra Express	336i PnP (Rockwell)	ISA	33.6K	OK
SmartLink	3334BAV (Lucent VALV34EMF))	ISA	33.6K	OK
CIS	WS-5614WD8 X2 (TI/USR)	ISA	56K	OK
CIS	WS-5614JDH K5Flex (Lucent)	ISA	56K	OK
USRobotics	USR X2	ISA	56K	OK
CPI	VIVA56LC-SM K5Flex (Lucent)	ISA	56K	OK
Digitan	ES560-448 K5Flex (Lucent)	ISA	56K	OK
	V1456VQH-T5 (Lucent)	ISA	56K	OK
CIS	V.90 WS-56149DD (Lucent)	PCI	56K	OK
CIS	WS-5614PS3 X2	PCI	56K	OK