How to let Bluetooth Icon shows when it is removed or disappear in Win8.1

Edited by MSI NB FAE Team | Version: 1.0 | Date: 2015/04/02

1. Please move cursor to right corner of screen, get the charm bar.



2. Search bluetooth, select “Change Bluetooth Settings”.



3.Enable “Show the Bluetooth icon in the notification area”, click Apply and OK to save setting.

