

## CD ROM DRIVES

The following CD-ROM drives were tested under Windows® 95, WinBench® 98 CD-ROM test.

MANUFACTURER	MODEL NUMBER		DOS6.22	WIN95	WINBENCH98
Panasonic	CR-584-B	12X	OK	OK	OK
Toshiba	XM-5702B	12X	OK	*OK	OK
GoldStar	CRD-8160B	16X	OK	OK	OK
Hitachi	CDR-8130	16X	OK	OK	OK
NEC	CDR-1600A	16X	OK	OK	OK
Panasonic	CR-585-B	16X	OK	OK	OK
SONY	CDU-511	16X	OK	OK	OK
TEAC	CD516E	16X	OK	OK	OK
VUEGO	616A-004	18X	OK	OK	OK
Mitsumi	CRMC-FX240S	24X	OK	OK	OK
NEC	CDR-1800A	24X	OK	OK	OK
Panasonic	CR-585-B	24X	OK	OK	OK
Philips	PCA243CD/M2	24X	OK	OK	OK
Pioneer	DR-A24X	24X	OK	OK	OK
TEAC	CD524E	24X	OK	OK	OK
Toshiba	XM-6102B	24X	OK	OK	OK
Aopen	CD-932E/AKU	32X	OK	OK	OK
Cyberdrive	321D	32X	OK	OK	OK
Mitsumi	CRMC-FX320S	32X	OK	OK	OK
NEC	CDR-1900A	32X	OK	OK	OK
Panasonic	CR-586-B	32X	OK	OK	OK
Philips	PCA323CD	32X	OK	OK	OK
Pioneer	DR-A04S	32X	OK	OK	OK
SONY	CDU711	32X	OK	OK	OK
TEAC	CD-532E	32X	OK	OK	OK
ASUS	CD-S340	34X	OK	OK	OK
AOpen	CD-936E/AKU	36X	OK	OK	OK

\*OK means the CD-ROM cannot run in DMA mode. We are currently looking for this problem.

## DVD ROM DRIVES

The following DVD-ROM drives were tested under Windows™ 95, play DVD and VCD, WinBench™ 98 CD-ROM test.

MANUFACTURER	MODEL NUMBER	WIN95	VCD & DVD	WINBENCH98
Creative	DVD2240E (Dxr2)	OK	OK	OK
Pionner	DVD-101	OK	OK	OK
Philips	DRD-5200/30	OK	OK	OK
Toshiba	SD-M1102	OK	OK	OK