

# Hard Disk Drive

## SCSI Hard Disk

System Configuration				
Device Configuration		Manufacturer	Model No.	Spec.
	Processor	Intel	3.2GHz	800MHz
	Memory	Samsung	M378T3253FG0-CD5	256MB X 1 DDR2 533
	VGA Card	Onboard		
	Lan Card	Onboard		
	Sound Card	Onboard		
	Hard Drive	As Follows		
	CD-ROM	Teac	CD-540E	40X
	Floppy Drive	Teac	FD-235HF	
	Power Supply	Jou Jye	JJ-300T 300W	
	Mouse	Acer	PS2	
	Keyboard	Acer	PS2	
Monitor	Acer	AcerView 77C	17"	
SW Info	VGA BIOS	3340		
	VGA Driver	6.14.10.3818		

No.		Model	Capacity	SCSI Card
01	IBM	DNES-309170 (Ultra Wide)	9.1GB	Adaptec AHA-2940UW (Ultra-Wide)
02		DDYS-T36950 Ultra-160	36.7 GB	Adaptec ASC-39160 Ver.B (Ultra 160)
03		Ultrastar IC35L036UWD210-0 Ultra-160	36GB	Adaptec ASC-39160 Ver.B (Ultra 160)
04		Ultrastar IC35L073UWD210-0 Ultra-160	73GB	Adaptec ASC-29160 Ver.B (Ultra 160)
05	QUANTUM	ATLAS 10K TN9100W Ultra-160	9.1 GB	Adaptec ASC-39160 Ver.A (Ultra 160)
06		Atlas 10K III KW73L018 Ultra-160	73.4GB	Adaptec ASC-29160 Ver.B (Ultra 160)
07	SEAGATE	ST336706LW Ultra-160	36.7 GB	Adaptec ASC-29160 Ver.B (Ultra 160)

No.	O.S. Installation	Result
01	WINXP	OK
02	WINXP	OK
03	WINXP	OK
04	WINXP	OK
05	WINXP	OK

No.	O.S. Installation	Result
06	WINXP	OK
07	WINXP	OK

## P-ATA Hard Disk

System Configuration				
Device Configuration		Manufacturer	Model No.	Spec.
	Processor	Intel	2.8GHz	800MHz
	Memory	Samsung	M378T3253FG0-CD5	256MB X 1 DDR2 533
	VGA Card	Onboard		
	Lan Card	Onboard		
	Sound Card	Onboard		
	Hard Drive	As Follows		
	CD-ROM	Sony	CDU5211	52X
	Floppy Drive	Teac	FD-235HF	
	Power Supply	Jou Jye	JJ-300T 300W	
	Mouse	Acer	PS2	
	Keyboard	Acer	PS2	
Monitor	Acer	AcerView 77C	17"	
SW Info	VGA BIOS	3340		
	VGA Driver	6.14.10.3818		

Model			Capacity	O.S. Installation	Driver Installation	Copy & Compare file	Result
Hitachi	7K250	HDS722525VLAT80	UD100 ; 250 GB	WINXP	OK	OK	OK
	7K250	HDS724040KLAT80	UD100 ; 400 GB	WINXP	OK	OK	OK
IBM	75GXP	DTLA-307075	UD100 ; 76.8 GB	WINXP	OK	OK	OK
	60GXP	IC35L060AVER07-0	UD100 ; 61.5 GB	WINXP	OK	OK	OK
	120GXP	IC35L080AVVA07-0	UD100 ; 82.3 GB	WINXP	OK	OK	OK
		IC35L120AVVA07-0	UD100 ; 123.5 GB	WINXP	OK	OK	OK
Maxtor	DiamondMax Plus D740X	D740X-6L(6L060J3)	UD133 ; 60 GB	WINXP	OK	OK	OK
		D740X-6L(6L080J4)	UD133 ; 80 GB	WINXP	OK	OK	OK
	DiamondMax D540X-4G	4G120J6	UD133 ; 120 GB	WINXP	OK	OK	OK
	Fireball 3	2F040J0	UD133 ; 40 GB	WINXP	OK	OK	OK
	DiamondMax 16	4R060J0	UD133 ; 60 GB	WINXP	OK	OK	OK
		4R060L0	UD133 ; 60 GB	WINXP	OK	OK	OK
		4A160J0	UD133 ; 160 GB	WINXP	OK	OK	OK
		4A250J0-1A	UD133 ; 250 GB	WINXP	OK	OK	OK
	DiamondMax Plus 8	6E040L0-1A	UD133 ; 40 GB	WINXP	OK	OK	OK
	MaxLine Plus II ATA	7Y250P0	UD133 ; 250GB	WINXP	OK	OK	OK
Quantum	Fireball Plus	AS40000AT	UD100 ; 40 GB	WINXP	OK	OK	OK
		AS60000AT	UD100 ; 60 GB	WINXP	OK	OK	OK
Samsung		SP4002H	UD100 ; 40 GB	WINXP	OK	OK	OK
		SV0602	UD100 ; 60 GB	WINXP	OK	OK	OK
		SV0802N	UD133 ; 80GB	WINXP	OK	OK	OK
		SP1604N	UD133 ; 160 GB	WINXP	OK	OK	OK
Seagate	Barracuda ATA III	ST340824A	UD100 ; 40 GB	WINXP	OK	OK	OK

		U Series	ST340823A	UD100 ; 40 GB	WINXP	OK	OK	OK	
		Barracuda ATA IV	ST360021A	UD100 ; 60 GB	WINXP	OK	OK	OK	
			ST380021A	UD100 ; 80 GB	WINXP	OK	OK	OK	
		Barracuda ATA V	ST380023A	UD100 ; 80 GB	WINXP	OK	OK	OK	
			ST3120023A	UD100 ; 120 GB	WINXP	OK	OK	OK	
		Barracuda 7200.7	ST380011A	UD100 ; 80 GB	WINXP	OK	OK	OK	
			ST3160023A	UD100 ; 160 GB	WINXP	OK	OK	OK	
	WD	Special Edition	Caviar 1200JB	UD100 ; 120 GB	WINXP	OK	OK	OK	
				Caviar 2500JB	UD100 ; 250 GB	WINXP	OK	OK	OK
		High-performance	Caviar 1200BB	UD100 ; 120 GB	WINXP	OK	OK	OK	
				Caviar 1800BB	UD100 ; 180 GB	WINXP	OK	OK	OK
				Caviar 2000BB	UD100 ; 200 GB	WINXP	OK	OK	OK

### S-ATA Hard Disk

System Configuration			
	Manufacturer	Model No.	Spec.
Device Configuration	Processor	Intel	3.2GHz 800MHz
	Memory	Infineon	Infineon HYS64T64000GU-3.7-A 512MB X 1 DDR2 533
	VGA Card	Onboard	
	Lan Card	Onboard	
	Sound Card	Onboard	
	Hard Drive	As Follows	
	CD-ROM	Teac	CD-540E 40X
	Floppy Drive	Teac	FD-235HF
	Power Supply	Jou Jye	JJ-300T 300W
	Mouse	Acer	PS2
	Keyboard	Acer	PS2
Monitor	Acer	AcerView 77C 17"	
SW Info	VGA BIOS	3340	
	VGA Driver	6.14.10.3818	

Model			Capacity	O.S. Installation	Shutdown 10x	Driver Installation	Copy & Compare file	Result
	Hitachi		HDS722516VLSA80	UD150 ; 160GB	WINXP	OK	OK	OK
			HDS724040KLASA80	UD150 ; 160GB	WINXP	OK	OK	OK
	Maxtor	DiamondMax Plus 9	6Y080M0	UD150 ; 80 GB	WINXP	OK	OK	OK
			MaxLine Plus II SATA150	7Y250M0	UD150 ; 250GB	WINXP	OK	OK
	Samsung		SP1612C	UD150 ; 160 GB	WINXP	OK	OK	OK
	Seagate	Barracuda Serial ATA V	ST380023AS	UD150 ; 80 GB	WINXP	OK	OK	OK
	WD	Enterprise	WD360	UD150 ; 36 GB	WINXP	OK	OK	OK
			Caviar WD2500JD	UD150 ; 250GB	WINXP	OK	OK	OK