

NETWORK ADAPTERS

The following network cards were tested under the operating system specified. Test procedures include connecting to server and copying directories and files.

MANUFACTURER	CHIPSET	O.S. ENVIRONMENT	REMARKS	
3COM	3C595 Rev C	Win98	PCI	OK
3COM	3C900-Combo	Win98	PCI	OK
3COM	3C905-TX	Win98/NW4.11	PCI	OK
3COM (LAN Wakeup)	3C905B-TX	Win98/NW4.11	PCI	OK
D-Link	DFE-530TX	Win98	PCI	OK
D-Link (LAN Wakeup)	DFE-500TX(Digital 21143-PD)	Win98	PCI	OK
Intel 557	Ether Express Pro/100 Ver B	Win98	PCI	OK
Intel 558 (LAN Wakeup)	Ether Express Pro/100 Ver B	Win98	PCI	OK
Intel 558	Ether Express Pro/100 Ver B	Win98	PCI	OK
Intel 558	Ether Express Pro/100 Ver B (2 ch)	Win98	PCI	OK
SMC	1211TX 10/100M	Win98	PCI	OK
Accton	EN1207B-TX (Digital 21140-AF)	Win98	PCI	OK
3COM	Etherlink III 3C509B-C Rev A	Win98	ISA	OK
D-Link	DE-220PCAT(224C)Rev B1	Win98	ISA	OK
Intel	Ether Express Pro/10	Win98	ISA	OK
Accton	EN1661	Win98	ISA	OK
Accton	EN1661R01	Win98	ISA	OK
Accton	EN1658-P	Win98	ISA	OK

IPX Boot ROM for Novell 3.1x & Novell 4.1x :

MANUFACTURER	CHIPSET	O.S. ENVIRONMENT	REMARKS	
3COM	3C900-Combo	Novell 4.11	PCI	OK
3COM	3C905-TX	Novell 4.11	PCI	OK