

## [How To] Nahimic 2 & 2+ Install & Update

Updating Nahimic and audio driver may help you to resolve the symptom listed below, so please follow the instruction to install/update the latest Nahimic and the audio driver released on MSI website.

- Weak audio sound or unbalanced audio sound output
- Crackling, distorted, popping sound or noise can be heard in specific web browser, games or video/audio players
- Noise, interference or intermittent sound in microphone recording
- Program crashes or black screen when running specific games, programs or video/audio players
- Nahimic audio effect settings can't be adjusted or the sound effect can't be applied with some program
- No pop-up window when an external audio device is plugged

- ❗ To know the latest features, update notes, improvements and its compatible audio driver for each Nahimic versions, please refer to [Release notes] [Nahimic 2](#), [Nahimic 2+](#).
- ❗ To find the general troubleshooting instructions of Nahimic, the overview of Nahimic settings and useful video tutorials, please refer to [Troubleshooting] [Nahimic 2](#), [Nahimic 2+](#).

1. Visit the driver download page of your product on MSI website and download the latest Nahimic and the audio driver.
2. **(Skip this step if you're performing a clean install)** Uninstall the old version of Nahimic and the audio driver.
  - ➔ *Search and run Control Panel > Uninstall a program > Double click on **Nahimic** and follow the on screen instruction to uninstall it.*
  - ➔ *Search and run Control Panel > Uninstall a program > Double click on the **Realtek audio driver** and follow the on screen instruction to uninstall it. (System reboot is required)*
3. Unzip the download file and install audio driver and Nahimic in turn.
  - ➔ *Double click on the "Setup.exe" in **audio driver** file and follow the on screen instruction to install it. (System Reboot is required)*
  - ➔ *Double click on the "Setup.exe" file in **Nahimic** file and follow the on screen instruction to install it.*
4. After the installation, reboot the system again to complete the update process.