

MEMORY MODULES

The following memory modules were tested under Windows™ 98, Winstoneâ 99, Tmem.exe.

DIMM :

Configuration :	
BIOS	W6153MS10viaB4
CPU	Intel® Celeron 366 MHz
VGA Card	Real 3D Starfighter (i740) AGP VGA Card
Hard Disk	Maxtor DiamondMax 90288D2 (2.8GB Ultra DMA 33) IDE Hard Disk
CD-ROM	SONY CDU711 32X IDE CD-ROM
FDD	NEC FD1231H 1.44MB FDD x 1
Mouse	Microsoft Mouse (PS/2)
PSU	Seasonic SS-250GTX Power Supply

MANUFACTURER	MODEL NUMBER	TYPE	SIZE	WINSTONE99	TMEM
Fujitsu	81117822E-100FN	SDRAM	16MB	OK	OK
SEC	KM48S2020AT-G10	SDRAM	16MB	OK	OK
Toshiba	TC59S1608AFT-10 (ECC)	SDRAM	16MB	OK	OK
Hitachi	HM5216805TT10	SDRAM	32MB	OK	OK
Hitachi (Ramstar)	HM5216805TT10H	SDRAM	32MB	OK	OK
NEC (Jaton)	D4516821AG5-A10-7JF	SDRAM	32MB	OK	OK
NEC (ARMAS)	D4564163G5-A10B-9JF	SDRAM	32MB	OK	OK
Mitsubishi (Ramstar)	M5M4V16S30BTP	SDRAM	32MB	OK	OK
Fujitsu (Jaton)	81117822E-100FN	SDRAM	32MB	OK	OK
LGS	GM72V16821CT10K	SDRAM	32MB	OK	OK
NEC	D4564841G5-A10-9JF	SDRAM	64MB	OK	OK

FOR PC100 DIMM :

BIOS	W6153MS10viaB4
CPU	Intel® Celeron 366 MHz
VGA Card	MS-4417 (SiS 6326) AGP VGA Card
Hard Disk	Fujitsu MPC3043AT (4.3GB Ultra DMA 33) IDE Hard Disk
CD-ROM	SONY CDU711 32X IDE CD-ROM
FDD	NEC FD1231H 1.44MB FDD x 1
Mouse	Microsoft Mouse (PS/2)
PSU	Seasonic SS-250GTX Power Supply

MANUFACTURER	MODEL NUMBER	TYPE	SIZE	WINSTONE99	TMEM
Apacer	AM2V168A1T8	SDRAM	32MB	OK	OK
LGS	GM72V661641CT7J	SDRAM	32MB	OK	OK

LGS (Apacer)	GM72V661641CTJ7	SDRAM	32MB	OK	OK
Micron	MT48LC4M16A2TG-8C	SDRAM	32MB	OK	OK
NEC (BUFFALO)	D4516821AG5-A10-7JF (ECC)	SDRAM	32MB	OK	OK
SEC	KM48S2020CT-GH (ECC)	SDRAM	32MB	OK	OK
SEC (BUFFALO)	KM48S2020CT-GH (ECC)	SDRAM	32MB	OK	OK
TI	TMS626812BDGE5H-8 (ECC)	SDRAM	32MB	OK	OK
Toshiba (ARMAS)	TC59S1608AFT-10	SDRAM	32MB	OK	OK
Vanguard	VG3617801CT-8H	SDRAM	32MB	OK	OK
Fujitsu (BUFFALO)	81F64842B-103FN (ECC)	SDRAM	64MB	OK	OK
Hitachi (PQI)	HM5264165TTB60	SDRAM	64MB	OK	OK
Hitachi (PQI)	HM5264805TTB60	SDRAM	64MB	OK	OK
Hyundai	HY57V658020ATC-74	SDRAM	64MB	OK	OK
Hyundai (PQI)	HY57V651620ATC-10S	SDRAM	64MB	OK	OK
LGS	GM72V66841CT7J	SDRAM	64MB	OK	OK
LGS (Apacer)	GM72V661641CT7J	SDRAM	64MB	OK	OK
Micron	MT48LC8M8A2TG-8C	SDRAM	64MB	OK	OK
Micron	MT48LC8M8A2TG-8B (ECC)	SDRAM	64MB	OK	OK
Mitsubishi (BUFFALO)	M5M4V64S30ATP (ECC)	SDRAM	64MB	OK	OK
NEC (BUFFALO)	D456841G5-A10-9JF (ECC)	SDRAM	64MB	OK	OK
NEC (PQI)	D4564163G5-A10B-9JF	SDRAM	64MB	OK	OK
SEC (BUFFALO)	KM48S8030BT-GH (ECC)	SDRAM	64MB	OK	OK
Toshiba (BUFFALO)	TC59S6408FTL-80H (ECC)	SDRAM	64MB	OK	OK
Fujitsu (BUFFALO)	81F64842B-103FN (ECC)	SDRAM	128MB	OK	OK
LGS (PQI)	GM72V66841CT7J	SDRAM	128MB	OK	OK
LGS	GM72V66841CT7J	SDRAM	128MB	OK	OK
NEC	D4564841G5-A10B-9JF)	SDRAM	128MB	OK	OK
SEC	KM48S8030BT-GH	SDRAM	128MB	OK	OK
SEC	KM48S16030T-GL	SDRAM	128MB	OK	OK
Toshiba (ARMAS)	TC59S6408FTL-80H	SDRAM	128MB	OK	OK
Toshiba (BUFFALO)	TC59S6408FTL-80H (ECC)	SDRAM	128MB	OK	OK
SEC	KM48S16030T-GL	SDRAM	256MB	OK	OK
Toshiba	TC59S6408FTL-80H	SDRAM	64MB	OK	OK
SEC	MT48LC8M8A2TG-8E	SDRAM	64MB	OK	OK