

## NETWORK ADAPTERS

The following network cards were tested under the operating system specified. Test procedures include connecting to server and copying directories and files.

MANUFACTURER	CHIPSET	O.S. ENVIRONMENT	REMARKS	
3COM	3C590-C Rev B	DOS 6.22	PCI	OK
3COM	3C595-C Rev C	SCO UNIX 5.0	PCI	OK
3COM	3C900-Combo	Windows 95 OSR2	PCI	OK
3COM	3C905-TX	Novell NetWare 4.11	PCI	OK
AMD	PCNet Rev C	Windows 95 OSR2	PCI	OK
D-Link	DFE-500TX(Digital 21140AE)	Windows 95 OSR2	PCI	OK
D-Link	DE-530CT+(Digital 21041PA)	Windows 95 OSR2	PCI	OK
Intel	Ether Express Pro 100	Windows 95 OSR2	PCI	OK
Intel	Ether Express Pro/100 Ver B	Windows NT 4.0	PCI	OK
Intel	S82558	Windows 95 OSR2	PCI	OK
SMC	EtherPower(Digital 21140AC)	Windows 95 OSR2	PCI	OK
SMC	9334BDT 10/100M (Digital 21140AC)	Windows 95 OSR2	PCI	OK
SMC	9432TX 10/100M	Windows 95 OSR2	PCI	OK
3COM	Etherlink III 3C509B-C	DOS 6.22	ISA	OK
3COM	Etherlink III 3C509B-C Rev A	Windows 95 OSR2	ISA	OK
D-Link	DE-220PCAT(224C)Rev B1	Windows 95 OSR2	ISA	OK
Intel	Ether Express Pro/10	Novell NetWare 3.12	ISA	OK
RMC	RTL 8019 PNP	Windows 95 OSR2	ISA	OK
Accton	EN1661	Windows 95 OSR2	ISA	OK
Accton	EN1661R01	Windows 95 OSR2	ISA	OK

IPX Boot ROM for Novell 3.1x & Novell 4.1x :

MANUFACTURER	CHIPSET	O.S. ENVIRONMENT	REMARKS	
3COM	3C900-Combo	Novell 4.11	PCI	OK
3COM	3C905-TX	Novell 4.11	PCI	OK